
| City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form |  | Page 1 of 3                                |
|--|--|--|
| Sewershed : Gwynn Falls  | Company : <u>URS</u>                     | Date: 07/02/2009                           |
| Test to be Performed : Smoke : X Dyed Water :                                  | Ground Condition :  Dry : X Damp : Wet : | Supervisor : Ryan Lamont                   |
| Manhole ID: S01WW_007MH  | Test ID: S1032-025011                    | Notifications (Residents, Fire, 311) : Yes |

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



| City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form |  | Page 2 of 3                                |
|--|--|--|
| Sewershed : Gwynn Falls  | Company : <u>URS</u>                     | Date : <u>07/02/2009</u>                   |
| Test to be Performed : Smoke : X Dyed Water :                                  | Ground Condition :  Dry : X Damp : Wet : | Supervisor : Ryan Lamont                   |
| Manhole ID: S01WW_007MH  | Test ID: S1032-025011                    | Notifications (Residents, Fire, 311) : Yes |

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Downspout Connection; Smoke: Medium; Status: Private Property


# Landscape



### Defect



ID



Location: N/A; Type: Downspout; Smoke: Medium; Status: Private Property

## Landscape




### Defect



| City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form |  | Page 3 of 3                                   |
|--|--|---|
| Sewershed : Gwynn Falls  | Company : <u>URS</u>                     | Date: 07/02/2009                              |
| Test to be Performed : Smoke : X Dyed Water :                                  | Ground Condition :  Dry : X Damp : Wet : | Supervisor : Ryan Lamont                      |
| Manhole ID: S01WW_007MH  | Test ID: S1032-025011                    | Notifications (Residents, Fire, 311) :<br>Yes |

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Downspout Connection; Smoke: Medium; Status: Private Property

# Landscape



## Defect

